

**AMPFIELD RECREATION GROUND Playground Inspection No. 2018 / 07**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	X	Pallet next to water tap + hardboard. Plastic containers next to eastern gate + breeze blocks	L	
Floor surface	✓			
Signs	✓			
Gates	X	Western end gate doesn't close properly	L	
Fences	X	From the eastern front fence 5 <sup>th</sup> upright loose, needs replacing. 5 <sup>th</sup> top bar needs replacing.	M	
Benches	X	Western bench is deteriorating and needs work to prevent wet timber becoming in contact with those sitting on the seat	M	
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			







**Date:** 25/03/2018      **Time Completed:** 13.30

**Weather Conditions:** Dry but overcast, no wind

**Additional Observations:** NONE

**Signature:**                      **Name:** Allan Clark

**AMPFIELD RECREATION GROUND INSPECTION** No. 2018 / 07

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion				
New Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins		Bin by White Horse PH is almost full Bin in car park is 25% full		

**Weather Conditions:**     **Dry but overcast, no wind**

**Additional Observations:**

**There are two GKN pallets which should be removed by the car park main gate.**

**Grass needs cutting on outfield.**

Signature:                    Name: Allan Clark

**Date: 25/03/2018**