

**AMPFIELD RECREATION GROUND Playground Inspection No. 2018 / 26**

<b>Auxiliary Items</b>	<b>OK?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
General Environment	Yes			
Floor surface	Yes			
Signs	Yes			
Gates	Yes			
Fences	No	South side 6 <sup>th</sup> section from east end; to strut broken and unattached to newel post at one end. Running repair made with Gaffer tape, strut needs replacement.	<b>L</b>	1 weeks
Benches	Yes			
<b>Equipment</b>	<b>OK?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
2 x Cradle Swings	Yes			
2x Flat Swings	Yes			
Stepping Pods	Yes			
Spinning Pole	Yes			
Two Up One down slide unit	Yes			
See-Saw	Yes			
Springers (2)	Yes			
Inclusive rotating dish	Yes			
Super Rope – End Swinger Mini	Yes			

**Date** 04/08/18      **Time Completed** 09.00

**Weather Conditions** Good

**Additional Observations**

Some other fence cross struts will need attention:

South side 7<sup>th</sup> section from east end; Central strut split in middle but secured to newel posts at each end.

West side 6<sup>th</sup> section from south end; central strut split in middle but secured to newel posts at each end.

Signature

Pete Edwards

**AMPFIELD RECREATION GROUND INSPECTION** No. 2018 / 26

<b>Area</b>	<b>OK?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
Entrances	Yes			
Pavilion	Yes			
New Container	Yes			
Outfield	Yes			
Site Boundaries, Fences and Hedges	Yes			
Bins	Yes			

**Weather Conditions**      Good

**Additional Observations**    None

Signature            Pete Edwards

**Date**    04/08/18