

**AMPFIELD RECREATION GROUND Playground Inspection No 2018/25**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	OK			
Floor surface	OK			
Signs	OK			
Gates		Gate nearest to carpark does not close		
Fences	Ok	OK		
Benches		Sharp edges on bench nearest car park	L	
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings		The plastic cover protecting the fixing of the chain to the swing is broken.	L	
2x Flat Swings	OK			
Stepping Pods	OK			
Spinning Pole	OK			
Two Up One down slide unit	OK			
See-Saw	Ok			
Springers (2)	OK			
Inclusive rotating dish	OK			
Super Rope – End Swinger Mini	OK			

**Date** .....30/07/2018..... **Time Completed** .....16:00.....

**Weather Conditions** Dry, some cloud

**Additional Observations** There is a hole dug close to the swings, c. 80 x 40mm . the centre gate appears to be secured by a chain but unlocked

Signature \_\_\_\_\_ Name G Roads.....

Signature \_\_\_\_\_ Name G Roads .....

**AMPFIELD RECREATION GROUND INSPECTION** No 2018 /25

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	OK			
PortaKabin and Container/kitchen	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	Ok			
Bins	OK	About 1/3 <sup>rd</sup> full		

**Weather Conditions** Dry some cloud

**Additional Observations** I did not enter the pavilion but a careful examination of the exterior suggested no issues.

Signature ..... Name ...G Roads.....

Signature ..... Name G Roads.....

Date 30/07/2018

**Date** .....