

AMPFIELD RECREATION GROUND Playground Inspection No. 2019 / 03

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	Yes			
Floor surface	Yes			
Signs	Yes			
Gates	Yes			
Fences	Yes			
Benches	Yes			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	Yes			
2x Flat Swings	Yes			
Stepping Pods	Yes			
Spinning Pole	Yes			
Two Up One down slide unit	Yes			
See-Saw	Yes			
Springers (2)	Yes			
Inclusive rotating dish	Yes			
Super Rope – End Swinger Mini	Yes			

Date 09/02/19 **Time Completed:** 13.30

Weather Conditions Fair

Additional Observations

- Playground north fence; 8th newel post from west corner, although not unsafe, is slightly loose in ground, appears to be rotting at base
- Playground south fence; immediately east of the metal double entry gate, the lowest horizontal strut had come away from the newel post. Hammered back during inspection but needs new nails.

Name: Peter Edwards.

AMPFIELD RECREATION GROUND INSPECTION No. 2019 / 03

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	Yes			
Pavilion	Yes			
Sewerage Plant (Listen)	Yes			
Container	Yes			
Outfield	Yes			
Site Boundaries, Fences and Hedges	Yes			
Bins	Yes			

Weather Conditions: Fair

Additional Observations

- Probably not significant but at the far south end of ARG, the ground was quite soggy after considerable rain the days before. No water was emitting from the ground drain outlet pipe protruding over the ditch at the east end. There was some water running into the ditch from the more westerly ground drain outlet pipe

Signature Name

Signature Name

Date 09/02/19