

AMPFIELD RECREATION GROUND Playground Inspection No. 2019 / 11

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	Yes			
Floor surface	Yes			
Signs	Yes			
Gates	Yes			
Fences	No	South fence east of central gate, first section. Lower horizontal rail is rotted and unsecured at the gate newel post end. The rail was hanging off with a nail protruding. Rail was pushed back by hand, but needs screwing into the newel post, possibly the rail to be completely replaced.	M	1 week
Benches	No	Playground bench on west side rotted at front seat edge with shards of soft rotten timber protruding.. The rotten timber was removed by hand. The seat edge needs sanding down to a smoother finish	L	2 week
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	Yes			
2x Flat Swings	Yes			
Stepping Pods	Yes			
Spinning Pole	Yes			
Two Up One down slide unit	Yes			
See-Saw	Yes			
Springers (2)	Yes			
Inclusive rotating dish	Yes			
Super Rope – End Swinger Mini	Yes			

Date 28/04/19

Time Completed: 09.30

Weather Condition: Fair

Additional Observations

- None

Name: Peter Edwards.

AMPFIELD RECREATION GROUND INSPECTION No. 2019 / 11

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	Yes			
Pavilion	Yes			
Sewerage Plant (Listen)	Yes			
Container	Yes			
Outfield	Yes			
Site Boundaries, Fences and Hedges	Yes			
Bins	Yes			

Weather Conditions: Fair

Additional Observations

- Pavilion external veranda lights permanently on. There appears to be a problem with PIR sensitivity

Name: Peter Edwards

Date 28/04/19