

**AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /02**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	X	Post on southern fence – 5 in from eastern side, is loose. (In hand with AC)	L	2 weeks
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

**Date** ...22/01/2018 ..... **Time Completed** .....11.30.....

**Weather Conditions;** bright, wet underfoot

**Additional Observations**

Signature ...Doreen Matthews... Name ...Bryan Nanson.....

Signature ..... Name .....

**AMPFIELD RECREATION GROUND INSPECTION** No 2018 /02

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

**Weather Conditions;** bright, wet underfoot.

**Additional Observations**

Signature      ... Doreen Matthews ...      Name      .....Bryan Nanson.....

Signature      .....  
Name .....

**Date**      .....22/01/2018