

AMPFIELD RECREATION GROUND Playground Inspection No. 2018/03

| Auxiliary Items | OK? | Issues | Risk L/M/H | Time Scale |
|-------------------------------|------------|---------------|-------------------|-------------------|
| General Environment | Yes | | | |
| Floor surface | Yes | | | |
| Signs | Yes | | | |
| Gates | Yes | | | |
| Fences | Yes | | | |
| Benches | Yes | | | |
| Equipment | OK? | Issues | Risk L/M/H | Time Scale |
| 2 x Cradle Swings | Yes | | | |
| 2x Flat Swings | Yes | | | |
| Stepping Pods | Yes | | | |
| Spinning Pole | Yes | | | |
| Two Up One down slide unit | Yes | | | |
| See-Saw | Yes | | | |
| Springers (2) | Yes | | | |
| Inclusive rotating dish | Yes | | | |
| Super Rope – End Swinger Mini | Yes | | | |

Date: 05/02/18

Time Completed: 11.00

Weather Conditions: Good

Additional Observations: None

Name Peter Edwards

AMPFIELD RECREATION GROUND INSPECTION No 2018/03

| Area | OK? | Issues | Risk L/M/H | Time Scale |
|---------------------------------------|------------|---------------|-----------------------|-------------------|
| Entrances | Yes | | | |
| Pavilion | Yes | | | |
| New Container | Yes | | | |
| Outfield | Yes | | | |
| Site Boundaries, Fences and Hedges | Yes | | | |
| Bins | Yes | | | |

Date: 05/02/18

Time Completed: 11.00

Weather Conditions: Good

Additional Observations: None

Name Peter Edwards