

AMPFIELD RECREATION GROUND Playground Inspection No 2018 /05

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	OK		L	
Floor surface	OK			
Signs	OK			
Gates		Gate nearest to carpark does not close		
Fences	Ok	OK		
Benches		Sharp edges on bench nearest car park	L	
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	OK			
2x Flat Swings	OK			
Stepping Pods	OK			
Spinning Pole	OK			
Two Up One down slide unit	OK			
See-Saw	Ok			
Springers (2)	OK			
Inclusive rotating dish	OK			
Super Rope – End Swinger Mini	OK			

Date12/03/2018..... **Time Completed**12:30.....

Weather Conditions Dry, very wet underfoot

Additional Observations Miniscule items of litter in the play area

Signature Name G Roads.....

Signature Name G Roads

AMPFIELD RECREATION GROUND INSPECTION No 2018 /05

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	OK			
PortaKabin and Container/kitchen	OK			
Outfield	OK			
Site Boundaries, Fences and Hedges	Ok			
Bins	OK			

Weather Conditions Dry very wet underfoot

Additional Observations I did not enter the pavilion but a careful examination of the exterior suggested no issues.

Signature Name ...G Roads.....

Signature Name G Roads.....

Date: 12/03/2018

Date