


AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /*

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date ...02/04/2018..... **Time Completed**17:30.....

Weather Conditions: Cloudy

Additional Observations

Signature  Name ...David Stevens.....

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No 2018 /*

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	X	Mole damage on golf course side of field. Dog pooh bag left on field	L	
Site Boundaries, Fences and Hedges	✓			
Bins	X	Pub = Full Car Park ¼ full		

Weather Conditions

Cloudy

Additional Observations

Signature  Name ...David Stevens.....

Signature Name

Date02/02/18.....