


AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /*

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	X	Hole near internal fence making it easy for a child to twist an ankle. Empty wine bottle found by seat.	M	
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date ...15/04/2018..... **Time Completed**13:00.....

Weather Conditions: Raining

Additional Observations

Signature  Name ...David Stevens.....

Signature Name


AMPFIELD RECREATION GROUND INSPECTION No 2018 /*

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	X	Un-bagged dog poo within boundary.	M	
Site Boundaries, Fences and Hedges	✓			
Bins	✓	Pub = Nearly Empty Car Park = Nearly Empty		

Weather Conditions

Cloudy

Additional Observations

Signature  Name ...David Stevens.....

Signature Name

Date15/02/18.....