

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 / 12

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	X	Pallet next to water tap + hardboard. Plastic containers next to eastern gate + breeze blocks	L	
Floor surface	X	Grass needs cutting	L	
Signs	✓			
Gates	X	Western end gate doesn't close properly	L	
Fences	X	From the eastern front fence 5 th upright loose, needs replacing. 5 th top bar needs replacing.	M	
Benches	X	Western bench is deteriorating and needs work to prevent wet timber becoming in contact with those sitting on the seat	M	
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date: 29/04/2018 **Time Completed:** 13.00

Weather Conditions: Dry but overcast.

Additional Observations: 4 x large Heineken beer cans left in playground area. Put them in the rubbish bin. Grass needs cutting inside the play area.

Signature:



Name: Allan Clark

AMPFIELD RECREATION GROUND INSPECTION No. 2018 / 12

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓	Bin by White Horse PH is a third full Bin in car park is quarter full		

Weather Conditions: Dry but overcast.

Additional Observations:

There are two GKN pallets which should be removed by the car park main gate.

By the White Horse car park entrance there is a sign saying “No dogs”. Requires removal or amendment.

Signature:



Name: Allan Clark

Date: 29/04/2018