

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /15

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	X	Post on southern fence – 5 in from eastern side, is loose. (In hand with AC). Loose arras rail repaired.	L	
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date ...20/05/2018 **Time Completed**09.30.....

Weather Conditions; bright

Additional Observations

Signature ... Bryan Nanson ... Name

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No 2018 /09

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓	Need emptying – due 25/05/18		

Weather Conditions; Sunny.

Additional Observations

Signature ... Bryan Nanson ... Name

Signature Name

Date ...20/05/2018