

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 / 18

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	X	Western bench is deteriorating and needs work to prevent wet timber becoming in contact with those sitting on the seat	M	
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date: 08/06/2018 **Time Completed:** 12.00

Weather Conditions: Dry but overcast.



Additional Observations: Signature:

Name: Allan Clark


AMPFIELD RECREATION GROUND INSPECTION No. 2018 / 18

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	X	Rubbish dumped next to western fencing in car park access area.	L	
Pavilion	✓			
New Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	X	Do we need to cut the nettles which are growing strongly by the ditch on the eastern boundary?	L	
Bins	✓	Bin by White Horse PH is full Bin in car park is half full		

Weather Conditions: Dry but overcast.

Additional Observations:

There are two GKN pallets which should be removed by the car park main gate.



Signature:

Name: Allan Clark

Date: 08/06/2018