

**AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /22**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

**Date** ...08/07/2018 ..... **Time Completed** .....09:15.....

**Weather Conditions;** Hot, bright sun

**Additional Observations**

Signature ...Bryan Nanson..... Name .....

Signature ..... Name .....

**AMPFIELD RECREATION GROUND INSPECTION** No 2018 /22

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓	Filled		

**Weather Conditions;** Hot, bright sun

**Additional Observations**

Signature ...Bryan Nanson..... Name .....

Signature ..... Name .....

**Date** ...08/07/2018 .....