

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /21

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date ...01/07/2018 **Time Completed**11.30.....

Weather Conditions; Bright sun

Additional Observations

Signature ... Doreen Matthews ... Name ... Bryan Nanson

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No 2018 /21

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓			

Weather Conditions; Bright sun

Additional Observations

Signature ... Doreen Matthews ... Name ... Bryan Nanson

Signature Name

Date ...01/07/2018