


**AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /19**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	X	Glass bottles left on ground. (now removed)		
Floor surface	✓	Hole near internal fence making it easy for a child to twist an ankle. Empty wine bottle found by seat.	M	
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

**Date** ...17/06/2018..... **Time Completed** .....17.20.....

**Weather Conditions:** Light Rain

**Additional Observations**

Signature .....  ..... Name ...David Stevens.....

Signature ..... Name .....


**AMPFIELD RECREATION GROUND INSPECTION** No 2018 /19

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✓			
Outfield	X	Slight rabbit damage inside cricket boundary.	L	
Site Boundaries, Fences and Hedges	✓			
Bins	X	Pub = Overflowing Car Park = ½ full.	M	

**Weather Conditions**

Light rain.

**Additional Observations**

Signature .....  ..... Name ...David Stevens.....

Signature ..... Name .....

Date .....17/06/18.....