

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 / 24

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	X	Grass needs cutting	L	
Signs	✓			
Gates	✓			
Fences	X	6 th top bar from the western end needs replacing 5 th post from the eastern end is loose and the top bar needs replacing.	M	
Benches	X	Western end bench is deteriorating and needs work to prevent wet coming in contact with those sitting on the seat.	M	
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date 22/07/18 **Time Completed** 11.30

Weather Conditions: **Very warm with occasional sun**

Additional Observations

Signature:

Name: Allan Clark

AMPFIELD RECREATION GROUND INSPECTION No. 2018 / 24

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✗	Despite using the APC key in the plastic jar I was unable to gain access to the kitchen. The door was un-locked but wouldn't move. Can't understand why? <i>Afternote: problem with lock identified by cricketers on 21 July. It unlocks only when lifted up, not pressed down. Builder to be notified. BWN</i>	H	
New Container	✓			
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✗	Pub = Overflowing Car Park = Empty Have moved refuse from pub bin to car park bin. Now both 2/3rds full	H	

Weather Conditions: Very warm with occasional sun

Additional Observations:

I would suggest we need a recycling bin because 40-50% of the refuse is recyclable, i.e., cans, plastic bottles and cardboard.

Signature:

Name: Allan Clark

Date 22/07/2018