

**AMPFIELD RECREATION GROUND Playground Inspection No. 2018 / 30**

| Auxiliary Items               | OK? | Issues | Risk L/M/H | Time Scale |
|-------------------------------|-----|--------|------------|------------|
| General Environment           | ✓   |        |            |            |
| Floor surface                 | ✓   |        |            |            |
| Signs                         | ✓   |        |            |            |
| Gates                         | ✓   |        |            |            |
| Fences                        | ✓   |        |            |            |
| Benches                       | ✓   |        |            |            |
| Equipment                     | OK? | Issues | Risk L/M/H | Time Scale |
| 2 x Cradle Swings             | ✓   |        |            |            |
| 2x Flat Swings                | ✓   |        |            |            |
| Stepping Pods                 | ✓   |        |            |            |
| Spinning Pole                 | ✓   |        |            |            |
| Two Up One down slide unit    | ✓   |        |            |            |
| See-Saw                       | ✓   |        |            |            |
| Springers (2)                 | ✓   |        |            |            |
| Inclusive rotating dish       | ✓   |        |            |            |
| Super Rope – End Swinger Mini | ✓   |        |            |            |

**Date** ...02/09/2018.....**Time Completed** ...09.45am.....







**Weather Conditions** Cool & bright

**Additional Observations**

Signature ..... Name ...Bryan Nanson.....

Signature ..... Name .....

**AMPFIELD RECREATION GROUND INSPECTION** No. 2018 /30

| Area                                  | OK?   | Issues | Risk<br>L/M/H | Time Scale |
|---------------------------------------|---|--------|---------------|------------|
| Entrances                             |    |        |               |            |
| Pavilion                              |    |        |               |            |
| New Container                         |    |        |               |            |
| Outfield                              |    |        |               |            |
| Site Boundaries,<br>Fences and Hedges |    |        |               |            |
| Bins                                  |  |        |               |            |

**Weather Conditions:** cool & bright

**Additional Observations**

Signature ..... Name ...Bryan Nanson.....

Signature ..... Name .....

**Date** .....02/09/2018.....