

**AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /37**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	X	The east gates is not closing. (Action in hand.)	L	
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date 21/10/2018 Time Completed 11.30

Weather Conditions







Overcast, wet underfoot.

Additional Observations

Signature ..... Name Doreen Matthews

Signature ..... Name Bryan Nanson

**AMPFIELD RECREATION GROUND INSPECTION** No. 2018 / 37

<b>Area</b>	<b>OK?</b>	<b>Issues</b>	<b>Risk L/M/H</b>	<b>Time Scale</b>
Entrances				
Pavilion				
New Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins				

**Weather Conditions**

Overcast

**Additional Observations**

Signature ..... Name Doreen Matthews

Signature ..... Name Bryan Nanson

**Date** 21/10/2018