

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /38

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment				
Floor surface				
Signs				
Gates		The west and east gates are not closing on their springs	L	
Fences				
Benches				
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings				
2x Flat Swings				
Stepping Pods				
Spinning Pole				
Two Up One down slide unit				
See-Saw				
Springers (2)				
Inclusive rotating dish				
Super Rope – End Swinger Mini				

Date 28/10/2018 Time Completed 12.00

Weather Conditions

Very cool and windy

Additional Observations

Signature Name Allan Clark

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No. 2018 / 38

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
New Container	✗	Parish Council store door doesn't lock	L	
Outfield	✓			
Site Boundaries, Fences and Hedges	✗	In the rubbish tip there is a plastic folding sign which shouldn't be there. I also removed a compost bag from the ditch between the cricket pitch and the golf course.	M	
Bins	✓	The recycling bin is 100% full and is not emptied until a week on Friday. Did TVBC empty it last week? The other two rubbish bins gate is 50% and the one by the pavilion is 90% full.		

Weather Conditions

Very cool and windy

Additional Observations

The boundary rope is still in place right around the outfield. I would have thought this should be wound up and stored away. This would allow TVBC when doing a "last of season cut" to run right across the outfield.

Signature Name Allan Clark

Signature Name

Date 28/10/2018