

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 /42

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	X	The east gate is not closing. (Action in hand.)	L	
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date 16/12/2018 Time Completed 13.00

Weather Conditions







Overcast, wet underfoot.

Additional Observations

Signature Name Bryan Nanson

Signature Name

AMPFIELD RECREATION GROUND INSPECTION No. 2018 / 42

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion				
New Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins		All emptied		

Weather Conditions

Overcast, wet underfoot

Additional Observations

Signature Name Bryan Nanson

Signature Name

Date 26/11/2018