

AMPFIELD RECREATION GROUND Playground Inspection No. 2018 / 43

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	Yes			
Floor surface	Yes			
Signs	Yes			
Gates	Yes			
Fences	Yes			
Benches	Yes			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	Yes			
2x Flat Swings	Yes			
Stepping Pods	Yes			
Spinning Pole	Yes			
Two Up One down slide unit	Yes			
See-Saw	Yes			
Springers (2)	Yes			
Inclusive rotating dish	Yes			
Super Rope – End Swinger Mini	Yes			

Date 30/12/18 **Time Completed:** 11.00

Weather Conditions: Fair

Additional Observations: East playground gate; spring needs adjustment as not closing properly

Signature Pete Edwards

AMPFIELD RECREATION GROUND INSPECTION No. 2018 / 43

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	Yes			
Pavilion	Yes			
New Container	Yes			
Outfield	Yes			
Site Boundaries, Fences and Hedges	Yes			
Bins	Yes			

Weather Conditions fair

Additional Observations None

Signature Pete Edwards

Date 30/12/18