

**AMPFIELD RECREATION GROUND Playground Inspection No. 2019 / 01**

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

**Date** ...13/01/2019... **Time Completed** .....







**Weather Conditions** Bright, dry underfoot

**Additional Observations**

Signature ..... Name Bryan Nanson....

Signature ..... Name .....

**AMPFIELD RECREATION GROUND INSPECTION** No. 2019 / 01

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion				
Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins				

**Weather Conditions**      Bright, dry underfoot

**Additional Observations**

Signature ..... Name Bryan Nanson .....

Signature ..... Name .....

**Date**    ...13/01/2019...