

AMPFIELD RECREATION GROUND Playground Inspection No. 2019 / 02

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓			
Signs	✓			
Gates	✓			
Fences	X	Post 5 from R (East) on S. fence } slight wobble Post 8 from L (West) on N fence }	L	
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date ...30/01/2019... **Time Completed** ...11.30am...







Weather Conditions cold, ice on grass, sun breaking through cloud

Additional Observations

Signature Name Bryan Nanson....

Signature Name Doreen Matthews...

AMPFIELD RECREATION GROUND INSPECTION No. 2019 / 02

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances				
Pavilion				
Container				
Outfield				
Site Boundaries, Fences and Hedges				
Bins				

Weather Conditions cold, ice on grass, sun breaking through cloud

Additional Observations

Signature Name Bryan Nanson

Signature Name Doreen Matthews....

Date ...30/01/2019...