

AMPFIELD RECREATION GROUND Playground Inspection No. 2019 / 08

Auxiliary Items	OK?	Issues	Risk L/M/H	Time Scale
General Environment	✓			
Floor surface	✓	But hole in front of the swings	M	
Signs	✓			
Gates	✓			
Fences	✓			
Benches	✓			
Equipment	OK?	Issues	Risk L/M/H	Time Scale
2 x Cradle Swings	✓			
2x Flat Swings	✓			
Stepping Pods	✓			
Spinning Pole	✓			
Two Up One down slide unit	✓			
See-Saw	✓			
Springers (2)	✓			
Inclusive rotating dish	✓			
Super Rope – End Swinger Mini	✓			

Date ...13/04/19..... **Time Completed**18.30.....

Weather Conditions - Fair

Additional Observations

Signature  NameDavid Stevens.....

Signature Name


AMPFIELD RECREATION GROUND INSPECTION No. 2019 / 08

Area	OK?	Issues	Risk L/M/H	Time Scale
Entrances	✓			
Pavilion	✓			
Sewerage Plant (Listen)	✓			
Container	✓	Rabbit hole damage – within cricket boundary on east of field.	L	
Outfield	✓			
Site Boundaries, Fences and Hedges	✓			
Bins	✓	Pub ¼ full. Car Park 2/3 full		

Weather Conditions

Fair

Additional Observations

Signature  NameDavid Stevens.....

Signature Name

Date13th April 2019.....