

**AMPFIELD RECREATION GROUND Playground Inspection No. 2019 / 17**

| Auxiliary Items               | OK? | Issues   | Risk L/M/H | Time Scale |
|-------------------------------|-----|--|------------|------------|
| General Environment           | ✓   |  |            |            |
| Floor surface                 | ✓   |  |            |            |
| Signs                         | ✓   |  |            |            |
| Gates                         | ✓   |  |            |            |
| Fences                        | X   | Lower arras rail 2 <sup>nd</sup> from right internal fence near rope swing will need attention soon. | L          | 3 weeks    |
| Benches                       | ✓   |  |            |            |
| Equipment                     | OK? | Issues   | Risk L/M/H | Time Scale |
| 2 x Cradle Swings             | ✓   |  |            |            |
| 2x Flat Swings                | ✓   |  |            |            |
| Stepping Pods                 | ✓   |  |            |            |
| Spinning Pole                 | ✓   |  |            |            |
| Two Up One down slide unit    | ✓   |  |            |            |
| See-Saw                       | ✓   |  |            |            |
| Springers (2)                 | ✓   |  |            |            |
| Inclusive rotating dish       | ✓   |  |            |            |
| Super Rope – End Swinger Mini | ✓   |  |            |            |

**Date** ...09/06/2019...      **Time Completed** ...1045...

**Weather Conditions**      mild & bright

**Additional Observations**

Signature .....      Name ..... Bryan Nanson ....

Signature .....      Name ... Doreen Matthews

**AMPFIELD RECREATION GROUND INSPECTION** No. 2019 / 15

| Area                                  | OK? | Issues | Risk<br>L/M/H | Time Scale |
|---------------------------------------|-----|--------|---------------|------------|
| Entrances                             | ✓   |        |               |            |
| Pavilion                              | ✓   |        |               |            |
| Container                             | ✓   |        |               |            |
| Outfield                              | ✓   |        |               |            |
| Site Boundaries,<br>Fences and Hedges | ✓   |        |               |            |
| Bins                                  | ✓   |        |               |            |

**Weather Conditions**      mild

**Additional Observations**

Signature ..... Name ..... Bryan Nanson ....

Signature ..... Name ... Doreen Matthews...

**Date** .. 09/06/2019...